

Fig. 1






Fig. 2



D-1561

3/20


Fig. 3



D-156/

4/20


Fig. 4



D-1561

5/20

Fig. 5






a)

19, 18, S4, S5, 21, 29, 24, S6, 22, 23, S7, 24, D1, D2

$\frac{7}{20}$

g. 7 (a)

Fig. 7 (a) is a schematic diagram of a mechanical assembly. It shows a main body (D1) with a tapered end (D2). A lever arm (18) is pivoted at one end (19) and has a roller (S4) at the other. A curved member (S6) is pivoted at one end (21) and has a roller (S7) at the other. A base (22) supports the assembly, with a roller (23) at the bottom. A component (24) is shown near the base. A small component (29) is also visible. Arrows indicate the direction of movement or force.



D-1561

9/20

Fig. 9 (a)




Fig. 9 (b)




Fig. 10 (a)




Fig. 10 (b)





Fig. 10 (c)



D-1561
11/20

Fig. 11(a)




Fig. 11(b)






Fig. 11(c)





13/20

D-1561
14/20

Fig. 14(a)





Fig.14 (b)



D-156/
15/20

Fig. 15(a)




Fig. 15(b)




Fig. 15(c)








Fig. 16










Fig. 19(a)




Fig. 19(b)





Fig. 19(c)



[illegible]